

DIMENSIONS

(SW01) ENCORDER
(SW02) PUSH ON SW

CLICK Position

Between A-C OFF
ON


Between B-C OFF
ON

CW direction

(SW01) OUTPUT

P.C.BOARD MOUNTING HOLE DIMENSIONS

(SW02)CIRCUIT DIAGRAM



DIMENSIONS

(SW01) ENCODER
(SW02) PUSH ON SW

CLICK Position

Between OFF
A-C ON



Between OFF
B-C ON

CW direction →

(SW01) OUTPUT

P.C.BOARD MOUNTING HOLE DIMENSIONS

(SW02) CIRCUIT DIAGRAM



DIMENSIONS

(SW01) ENCORDER
(SW02) PUSH ON SW

CLICK Position

Between A-C OFF
ON


Between B-C OFF
ON

CW direction

(SW01) OUTPUT

P.C.BOARD MOUNTING HOLE DIMENSIONS

(SW02)CIRCUIT DIAGRAM



DIMENSIONS

(SW01) ENCORDER
(SW02) PUSH ON SW

CLICK Position

Between A-C OFF
ON

Between B-C OFF
ON

CW direction

(SW01) OUTPUT

P.C.BOARD MOUNTING HOLE DIMENSIONS

(SW02)CIRCUIT DIAGRAM